



॥
२३/४/२१

भारत सरकार
GOVERNMENT OF INDIA

केंद्रीय लोक निर्माण विभाग CENTRAL PUBLIC WORKS DEPARTMENT
कार्यपालक अभियंता - त्रिवेन्द्रम O/o Executive Engineer - Trivandrum
'सी' विंग, पहली मंजिल, सी. जी. ओ कॉम्प्लेक्स, 'C' Wing, 1st Floor, C.G.O. Complex
पूंकुलम, वेल्लायणी पी.ओ. Poonkulam, Vellayani P.O.
तिरुवनंतपुरम 695522 - Thiruvananthapuram - 695 522



क्र.: 23(202)/EE-T/2021/ 704

Date: 17.04.2021

सेवा में

The principal,
Kendriya Vidyalaya
CRPF Campus, Pallipuram,
Trivandrum


विषय: Safety and security certificate for Kendriya Vidyalaya Pallipuram School
Building - reg.

संदर्भ: Your office letter No. Misc/KVPPM/2020-21/328 dated 29.12.2020.

Sir,

With reference to the letter cited above, the Safety Certificate of the School
building of Kendriya Vidyalaya, Pallipuram, Trivandrum is enclosed herewith for further
necessary action.

भवदीय,


(पी. एन. रामकृष्ण पिल्लै)
कार्यपालक अभियंता
केंद्रीय लोक निर्माण विभाग
तिरुवनंतपुरम

Office for Record.

प्रतिलिपि

Assistant Engineer, TCSD - III, CPWD, Trivandrum for information w.r.t. his
letter No. 23(29)/TCDS- III/CPWD/2020-21/118 dated 17.04.2021.




Attested
K. M. S. R.
23/4/21

प्राचार्य/PRINCIPAL
केंद्रीय विद्यालय/Kendriya Vidyalaya
सी आर पी एक पल्लीपुरम/CRPF Pallipuram
तिरुवनंतपुरम/Thiruvananthapuram 695316

कार्यपालक अभियंता
केंद्रीय लोक निर्माण विभाग

CERTIFICATE


This is to certify that the Kendriya Vidyalaya Building CRPF Campus at Pallipuram has been inspected by me on 16.04.2021 and found that building is structurally safe. However, some cracks/spalling in chajja-fins and leakage at many places are observed which may got rectified to avoid any mishap.



(पी. एन. रामकृष्ण पिल्लै)


कार्यपालक अभियंता

कें.लो.नि.वि., त्रिवेंद्रम

Officer for Record




Attended
K. M. R.


20/5/21
प्राचार्य/PRINCIPAL
केंद्रीय विद्यालय/Kendriya Vidyalaya
सी आर पी एक पल्लीपुरम/CRPF Pallipuram
तिरुवनंतपुरम/Thiruvananthapuram 695316